

**ABSTRACT****METHOD**

5 Kits, applicators and methods for treatment of a surface involve sequential application to a surface of a hydrogel precursor and a crosslinking component to form a removable hydrogel patch on the surface followed by removal of the patch. The method is suitable for removal of a stain from  
10 a surface.